



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
July 12

Repair Work

Devil's Slide (post mile 39.14)

- Level 'B' (lower level ocean side) – Drilling for tie backs continued using the reach over rig. 57 of 58 tie backs now installed. Tie back stressing also continued.



Drilling for the last tie back at level B



Cutting off excess after cables are tightened – level A

- Level 'D' (upper level cliff side) – Drilling for tie backs continued today from the temporary bench. 27 of 33 now installed.

Retaining (micropile) Wall

- Drilling and driving steel piles continued today. 44 of 99 now installed.



Drilling for micropiles

Rock Bolts Above The Road

- Drilling continued today to install 50 rock bolts above the level D bracing wall. These 15 feet long bolts will knit fractured rocks together reducing the risk rocks falls.



Drilling for rock bolts

Public Information

- Caltrans invited news crews to a media day at the repair site today. Approximately 20 reporters and photographers attended from newspapers, television and radio stations. The event was held to mark completion of 50% of the repair work.